




Model 540 WDK

Wire Dressguard Kit Required when fitting Windsor Arch Fronts to 922 Adorn Fireplace





Model 540 WDK is required for all 922 Adorn Fireplace installations fitted with 539/549 Windsor Arch Cast fronts.





Step 4 – Fasten casting to brackets on firebox and hang inner casting within arch on 2 hooks. Install wire guard as shown.





Step 3 – Install canopy shield
Insert one corner of the shield into the corner
behind the cast frame as shown. Bend the canopy
shield to a slight radius while inserting the other
corner behind the cast frame as shown (it may be
necessary to loosen canopy bolts). With both the
corners behind the cast frame, snap the shield
forward to follow the curve of the cast iron
canopy. The top of the shield should fit under the
projecting ledge in the casting as shown.